Colesville Depot -- No. 500709

Category Subcategory Administering Agency

Planning Area

Transportation
Highway Maintenance
Public Works & Transportation

Aspen Hill

Date Last Modified

Required Adequate Public Facility

Relocation Impact Status No None.

Planning Stage

January 07, 2008

EXPENDITURE SCHEDULE (\$000)

Cost Element	Total	Thru FY07	Est. FY08	Total 6 Years	FY09	FY10	FY11	FY12	FY13	FY14	Beyond 6 Years
Planning, Design, and Supervision	788	0	0	788	0	304	344	140	0	0	0
Land	0	0	0	0	0	0	0	0	0	0	0
Site Improvements and Utilities	0	0	0	0	0	0	0	0	0	0	0
Construction	0	0	0	0	0	0	0	0	0	0	0
Other	0	0	0	0	0	0	0	0	0	0	0
Total	788	0	0	788	0	304	344	140	0	0	0

FUNDING SCHEDULE (\$000)

G.O. Bonds	788	0	0	788	0	304	344	140	0	0	0
Total	788	0	0	788	0	304	344	140	0	0	0

DESCRIPTION

This project provides for the planning, design of an expanded Colesville Depot, currently operated by the Division of Operations, Highway Maintenance Section for the purpose of providing road maintenance for the southeastern portion of the County. The Depot site includes 11.5 acres of open land that adjoin Colesville Park and Paint Branch Park on Cape May Road. Major components of the project include: new outdoor storage canopy for maintenance vehicles, replacement of salt and sand domars with new operations barn, improved stormwater management, expansion of service bays, upgrade and relocation of offices, expansion of crew room, new bunk room, roof replacement, upgrade of existing rest rooms, repainting of all interior walls, replacement of ceiling tiles, re-pointing of masonry, refinishing of exterior surfaces and windows, and upgrading mechanical, electrical, communications and security systems.

COST CHANGE

Increase due to inflation.

JUSTIFICATION

The Colesville Depot, built in 1982, includes a series of 22-year old structures that have experienced significant demands resulting from increasing maintenance operations for new roadway infrastructure in this portion of the County. The Depot building is comprised of a one-story structure of approximately 7,300 square feet. The general areas of the interior spaces of the building are worn by years of use and require architectural improvements. The main building roof requires replacement. The vehicle maintenance bays are insufficient to service the majority of vehicles that are maintained within them. Existing salt and sand domars are in poor structural condition.

OTHER

This project is located in the Paint Branch Special Protection Area.

OTHER DISCLOSURES

- A pedestrian impact analysis has been completed for this project.

APPROPRIATION AND EXPENDITURE DATA						
Date First Appropriation	(\$000)					
First Cost Estimate Current Scope	FY07	595				
Last FY's Cost Estimate	595					
Appropriation Request	0					
Appropriation Request Est.	788					
Supplemental Appropriation R	0					
Transfer	0					
Cumulative Appropriation	0					
Expenditures / Encumbrances	0					
Unencumbered Balance	0					
Partial Closeout Thru	FY06	0				
New Partial Closeout	0					
Total Partial Closeout	0					

COORDINATION

Department of Public Works and Transportation (DPWT) Department of Technology Services (DTS) Department of Permitting Services (DPS) Maryland-National Capital Park and Planning Commission (M-NCPPC)

MAP

See Map on Next Page

